OFS Instruction Sheet

General Instructions

640-252-036-1 Issue 6, June 2006

ST® Connectors Instruction for Use


WARNING!

User should be aware of possible hazards due to presence of invisible (infrared) radiation when examining connectors with the naked eye or a microscope. A laser IR detection card (Edmund Industrial Optics #NT55-292 or equivalent) may be used to allow visualization of invisible IR light.

Material used in cleaning (isopropyl alcohol and canned air) should be used in a well ventilated area and not near an open flame. Follow all of the manufacturer's safety and disposal instructions. KEEP OUT OF REACH OF CHILDREN.

Install ST Connectors onto Coupling


- Install the connectors onto the coupling by aligning the mark on the rim of the connector body
 with the slot in the coupling. Complete the connection by pushing the connector onto the coupling
 with a clockwise twist-locking motion.
- If a high-loss condition exists, use the ST cleaning procedures and reinstall the connectors as described in Step 1.
- When doing rearrangements or reinsertions of ST connectors, use the ST cleaning procedures to clean all components and reinstall the connectors as described in Step 1.



Clean ST Connector, Coupling, and Attenuator


Clean connector ferrule with a wipe moistened with isopropyl alcohol* and blow-dry with canned air. Clean end and sides of ferrule.

Caution: Signal strength will be affected if ferrule is not thoroughly cleaned.




Clean coupling by placing a pipe cleaner (moistened with isopropyl alcohol*) inside coupling and gently rotating. Blow-dry the coupling using canned air.

Caution: Do not try to clean the coupling with pipe cleaner if a connector is mounted in one side.



Clean attenuator by holding canned air nozzle 3 inches from attenuator end. **Caution**: Do not use a pipe cleaner to clean attenuator.





OFS FIBER OPTIC TECHNICAL ASSISTANCE

1-888-FIBER HELP (1-888-342-3743)

* For cleaning, always use isopropyl alcohol (>91% 2-propanol + water).

Comcode 106 029 408


Copyright© 2006 OFS All Rights Reserved Printed in U.S.A. Page 1 2 Pages

640-252-036-1 Instruction Sheet

SC and LC Connectors Instruction for Use


Install SC Connectors onto Coupling

- Install each connector into the coupling by aligning the key on the connector body with the keyway on the coupling. The connector is properly installed when the white line in the grip disappears inside the coupling.
- If a high-loss condition exists, use the SC cleaning procedures and reinstall the connectors as described in Step 1.
- When doing rearrangements or reinsertions of SC connectors, use the SC cleaning procedures to clean all components and reinstall the connectors as described in Step 1.



Clean SC Connector, Coupling, and Attenuator

Clean connector ferrule with a wipe moistened with isopropyl alcohol* and blow-dry with canned air. Clean end and sides of ferrule.




Clean coupling by placing a pipe cleaner (moistened with isopropyl alcohol*) inside coupling and gently rotating. Blow-dry the coupling using canned air.

Caution: Do not try to clean the coupling with pipe cleaner if a connector is




Clean attenuator by holding canned air nozzle 3 inches from attenuator end.

Caution: Do not use a pipe cleaner to clean attenuator.



Install LC Connectors into Adapter

- Install connector(s) into the adapter by aligning the latch(s) on the connector(s) with the slot(s) on the adapter and gently push into place. An audible click is heard when the connector(s) snap into the adapter.
- If a high-loss condition exists, use the LC cleaning procedures and reinstall the connector(s) as described in Step 1.
- When doing rearrangements or reinsertions of LC connectors, use the LC cleaning procedures to clean all components and reinstall the connectors as described in Step 1.



Clean LC Connector and Adapter

Clean connector ferrule with a wipe moistened with isopropyl alcohol* and blow-dry with canned air. Clean end and sides of ferrule.

Caution: Signal strength will be affected if ferrule is not thoroughly cleaned.



Clean adapter by placing an adapter brush (moistened with isopropyl alcohol*) inside adapter and gently rotating. Blow-dry the adapter using canned air. The brush can be cleaned with alcohol and canned air.



If access to the adapter is only available from one side, use canned air to blow inside of adapter.



Warning: Do not try to clean adapter with a standard pipe cleaner. The LC's sleeve inner diameter is too small. Also, do not try to clean the adapter with LC adapter brush if a connector is mounted in the

Clean attenuator by holding canned air nozzle 3 inches from end of the attenuator. Blow air into each side of the attenuator.

Caution: Do not use pipe cleaner or adapter brush to clean attenuator.



OFS FIBER OPTIC TECHNICAL ASSISTANCE

Leading Optical Innovations

1-888-FIBER HELP (1-888-342-3743)

* For cleaning, always use isopropyl alcohol (>91% 2-propanol + water).

Page 2 2 Pages

Comcode 106 029 408